

1/4

P 111 438




FIG 1

4/4

P 111 438

	P1	P2	P3	P4
P1	d=0 t=0	d=0 t=0	d=12 t= 3 ms	d=8 t= 2 ms
P2	d=0 t=0	d=0 t=0	d=8 t= 2 ms	d=12 t= 3 ms
P3	d=16 t= 3 ms	d=13 t= 2 ms	d=0 t=0	d=0 t=0
P4	d=13 t= 2 ms	d=16 t= 3 ms	d=0 t=0	d=0 t=0

FIG 4